



Hindustan Oil Exploration Company Limited

'Lakshmi Chambers', 192, St. Mary's Road, Alwarpet, Chennai - 600 018. INDIA.

☎ : 91 (044) 66229000 • Fax: 91 (044) 66229011 / 66229012

E-mail: contact@hoec.com • Website: www.hoec.com CIN: L11100GJ1996PLC029880

June 03, 2024

By Online

The Listing Department National Stock Exchange of India Ltd., "Exchange Plaza", Bandra Kurla Complex, Bandra (East), Mumbai – 400 051 Stock Code: HINDOILEXP	The Corporate Relationship Department BSE Limited 1 st Floor, P. Jeejeebhoy Towers, Dalal Street, Mumbai – 400 001 Stock Code: 500186
--	--

Dear Sir/Madam,

Sub: Submission of information pursuant to Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015

In furtherance to our intimation dated May 29, 2024, we wish to inform that, in order to flow both the wells D1 & D2 to its optimum production, the oil export flowline needs to be flushed to increase the flow rate. Steam and hot water flushing of the export flowline started and in consequence the wells are shut-in from 10:00 hours on 3rd June 2024. On completion of flushing of export flowline, both the wells will be lined up for production, which will be informed to the exchanges.

Further, in terms of SEBI circular SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated July 13, 2023, the additional information required is given in Annexure - I.

The above information is also available on the website of the Company - www.hoec.com. We request you to kindly take our above submission on record.

Thanking you,
Yours Sincerely,

For Hindustan Oil Exploration Company Limited

G. Josephin Daisy
Company Secretary

Annexure I

Expected quantum of loss / damage caused	Nil
Whether loss / damage covered by insurance of not including amount	Not Applicable
Estimated impact on the production / operations in case of strike / lockouts / disruption	Nil
Factory / unit where the strike / lockout / disruption takes place including reasons for such strike / lockout / disruption	Western offshore B-80 field